CAROLINA'S HOME MEDICAL EQUIPMENT INCORPORATED

Invacare Home Fill Troubleshooting

Is the concentrator on? If it is making a loud beeping sound turn it off, press reset button and turn back on.

What liter flow is concentrator set on? If >3.0 then lower to ≤ 3.0

Is the homefill tank turned to the off position (for conserver) or "O" for continuous flow tank?

Is the connector tube between concentrator and HFill unit engaged? If broken it must be replaced in order to fill a tank.

Did you manually turn HFIll machine off between refills?

Is the tank properly engaged? Take tank off, turn off top machine (HFill) then re-engage tank (brass in brass) by pushing down with left hand on neck of tank, and pulling up on silver collar at the same time until you hear a decisive click. Then turn top machine on - The O2 below normal or wait light will stay on 2-3 minutes then tank should start filling.

If tank still does not fill either:

1. There's a leak in the HFill tank (listen for leak), try filling other tank.

2. If still bad the O2 purity is low in the concentrator or the sensor in the homefill unit is bad. Send Technician.